Length deck

45 ft 0 in / 13.72 m



ED BURNETT 45 FT GAFF RIGGED PILOT CUTTER 2008/2025



Specification

MISCHIEF

ED BURNETT 45 FT GAFF RIGGED PILOT CUTTER 2008/2025

Designer	Ed Burnett	Length waterline	38 ft 0 in / 11.58 m	Engine	Beta Marine 75 hp Diesel
Builder	RB Boatbuilding Ltd., Bristol	Beam	13 ft 0 in / 3.96 m	Location	United Kingdom
Date	2008	Draft	$7 \mathrm{ft} 6 \mathrm{in} / 2.29 \mathrm{m}$	Price	GBP 260,000
Length overall	59 ft 9 in / 18.2 m	Displacement	25 Tonnes		

Construction

These details are provisional and may be amended

Carvel larch on oak

Specification

BROKER'S COMMENTS

MISCHIEF is the fabulous result of naval architect Ed Burnett and traditional boatbuilder John Raymond-Barker's deeply informed research in creating an as near as possible replica of the 1906 Thomas Baker of Cardiff designed and built original Bristol Channel Pilot Cutter - internationally famous in the 1954 to 1968 ownership of mountaineer, explorer, voyager, and author H.W. "Bill" Tilman. Since her 2008 launch at Bristol, MISCHIEF has been a much loved, far travelled, and well proven family cruiser in the Mediterranean, on Spain's Atlantic seaboard, the West Coast of Scotland, and more recently in the Westcountry of England.



- SANDEMAN YACHT COMPANY
 - Brokerage Of Classic & Vintage Yachts

www.sandemanyachtcompany.co.uk



ED BURNETT 45 FT GAFF RIGGED PILOT CUTTER 2008/2025

Specification

REFIT & MAINTENANCE

2024-2025

HOPPER TRADITIONAL BOAT WORKS, PENRYN

HULL

- Extensive planking repairs under the counter to Lloyd's standards
- Planking repairs in larch; king plank in oak
- Starboard sheer plank replaced fwd and aft; top edge replaced midships
- Midrib replaced in oak
- Complete rebuild of arch board and transom assembly
- Internal counter deep cleaned, treated, and repainted
- Lands in the counter re-pitched
- Repairs to starboard knighthead and covering board at bowsprit aperture
- Starboard chainplates removed and refitted
- Backstay chainplates removed and refitted both sides
- Steelwork cleaned, treated, and repainted
- New anodes fitted
- Propeller serviced
- Hull sanded and antifouled with two coats
- Topsides repainted

DECK

- Extensive deck re-planking in Douglas fir; oak king planks
- Deck seams raked, treated, oakum caulked, Jeffery's pitched
- Deck beams around cockpit repaired or replaced as needed
- Starboard cockpit well replaced; fore and aft areas repaired
- Cockpit grating and compass mount repaired and refinished
- Cockpit coaming removed, repaired, and refitted
- Mainsheet horse removed, remade, and refitted; wing bolts added
- $\ensuremath{\text{Beam}}$ ends sistered onto deck beams to support cut-back soft planks
- Oak margin boards added around cockpit, companionway, and coachroof
- Companionway hatch removed, repaired, and refitted
- Entire new coachroof with oak sides and glassed ply over T&G decking
- Butterfly and sliding hatches repaired and refitted
- Dorade vents repaired with new cowls fitted
- GPS mount repaired, refitted, and fitted with new unit
- Deck prism removed and reinstalled in correct orientation
- Gas locker removed, refitted with new gas line
- Liferaft mounts replaced in iroko
- Staysail sheet lead fabricated in iroko
- Starboard quarter post replaced in oak
- Bulwark planking replaced as needed in larch
- Windlass serviced
- Gammon iron replaced
- Bar cleats removed and refitted

- Extensive covering board replacement in oak
- Gallows removed and refitted
- Rudder top bearing plate (steel) removed and refitted
- Brightwork stripped and revarnished
- Full repaint on deck

INTERIOR & SYSTEMS

- Cabin and cupboard doors repaired and refitted
- Door catches serviced
- Lighting and wiring repaired where required
- Engine and plumbing winterised and recommissioned
- Full deep clean and mould treatment
- T&G and oak posts replaced at companionway to access cockpit beams
- New Morse control fitted and systems removed/refitted
- Battery charger and consumer unit refitted
- Electrical audit conducted to check earthing
- Paint and varnish patched where necessary

RIGGING & SPARS

- Full de-rig, mast, spars, rigging
- Mast foot repaired
- mast, spars, and blocks stripped, checked, and varnished; checks filled with Ettan
- New oak spreaders installed
- New jib furling unit fitted
- New jib halyard and Dyneema backstays fitted
- Rigging tweaked and mast rake adjusted to reduce weather helm and improve ease of sailing
- Belay pins treated in linseed oil bath

2018-19

DENNIS PLATTEN TRADITIONAL RIGGING, UNDERFALL YARD, BRISTOL

- All standing and running rigging replaced

2017-2019

By RB BOATBUILDING, UNDERFALL YARD, BRISTOL

- Deck planks aft of the mast, beneath cockpit and in the lazarette tested
- where soft replaced
- All deck seams re-routed and re-caulked
- New electrical panel fitted with watertight connection box behind
- Shore power installed
- New Morsø 'Squirrel' stove fitted
- Faucets and shower heads renewed
- Forward and aft heads renewed $\,$
- Beta Marine engine was overhauled/ complete service
- Aqua drive and shaft were replaced
- New 3-blade folding Max Prop fitted
- New Rocna 33 kg anchor
- New roller gear fitted for anchor mounting on bow
- Sails cleaned and stored
- New oak tiller

- New Isotherm 50 L top loading fridge
- New No. 3 Jib
- New Jon-Buoy

Specification

HISTORY

"I think we all agree... that Tilman was pretty hard on his cutters, but that after all is what they were built for, not for posterity anyway."

So wrote MISCHIEF's builder, John Raymond-Barker in a 2003 internet forum when, together with naval architect Ed Burnett, he was seeking the lines of mountaineer, explorer, voyager, and author H.W. "Bill" Tilman's Bristol Channel Pilot Cutter MISCHIEF.

a half-model by their builders, then constructed quickly in the time-honoured way; to do a job; that they did very well - and after sail gave way to motor, many became enjoyed as excellent long distance cruising yachts.

This MISCHIEF's lines instead result from Burnett and Raymond-Barker's deeply informed research in creating an as near as possible replica of the 1906 Thomas Baker of Cardiff designed and built original, which became internationally famous through Tilman's ownership from 1954 until her 1968 loss at Jan Mayen in the Arctic Ocean.

And thus, posterity was in fact achieved. And thank goodness for it. The original MISCHIEF became surely the most universally known of the pilot cutters. What an exciting project and wonderful result.

Completed and launched in 2008, MISCHIEF has became a much loved family cruiser and sailed extensively in the Inner and Outer Hebrides from her Oban base. She participated in the Scottish Islands Peaks Race before heading south in 2013. After stops in the Scillies, Northern France and La Rochelle, she crossed the Bay of Biscay to a new home in Vigo in north west Spain. Two years of wonderful Galician cruising followed, the highlight being the annual cruise with locals around the Cies Islands.

In 2015 MISCHIEF passed through the Straight of Gibraltar bound for Mallorca, where she (very slowly) circumnavigated the island - over a blissful two years! In 2017 she was bound for home and a refit in her home port of Bristol under the watchful eye of her original builder.

The refit was completed in 2019 and she was sailed to Gweek, Cornwall to over-winter, ready for the new season. And then sadly for us all Covid-19 They never did 'just find' her lines: after all, these were boats first sculpted as struck. MISCHIEF has been lightly used since, spending winters until 2024 safely alongside Gweek Quay and summers on her mooring in St. Just in Roseland (possibly the best kept secret in the South West of England).

> The extensive 2024-2025 structural refit by Ben Hopper at Penryn is detailed above. MISCHIEF re-launched in May 2025 and immediately joined the Pilot Cutters Review at Falmouth.

©2025 Iain McAllister/ Sandeman Yacht Company Ltd.

Specification

CONSTRUCTION

- Larch planking
- Oak centreline
- Sawn oak frames c $70~\mathrm{mm}$ x $130~\mathrm{mm}$ @ c $550~\mathrm{mm}$ centres
- Copper fastened
- Bilge stringers 130 mm x 50 mm
- Internal, fixed lead pig ballast
- Full wood keel length 20 mm galvanised steel protection band
- Douglas fir traditional deck $1\frac{3}{4}$ in / 44 mm
- straight laid; nibbed to covering boards
- Oak deck beams c $100~\mathrm{mm}$ x $65~\mathrm{mm}$ @ $650~\mathrm{mm}$ centres
- Full length beam shelf $130 \times 60 \text{ mm}$
- Iroko deck structures

Specification

DECK LAYOUT, EQUIPMENT AND GROUND TACKLE

GENERAL

- Stanchioned, fully scuppered bulwarks; belaying cleats
- Iroko painted capping rail
- All new galvanised guard rail stanchions
- 4 x Belaying cleats at painted inner bulwarks

AFT DECK

- Open taffrail with fairleads
- Bronze Panama mooring fairleads port and starboard
- Galvanised and painted main sheet horse; rubber buffers

SIDE DECKS

- Deck light forward

- 2 x Deck prisms port and starboard
- Padeyes for runners and headsail sheeting
- Ash and bronze runner blocks

- Leading to Aft Pilot Cabin

- Panama mooring fairleads port and starboard
- Stove pipe socket
- Pin rails port and starboard

- Ash and bronze mainsheet blocks
- Bronze mushroom vent
- Boom gallows
- Galvanised and painted rudder head fittings; iroko fashioned bush
- Oak tiller
- Oak Sampson posts port and starboard

COCKPIT

- Large for a pilot cutter
- Well type with deck as seating
- Varnished iroko vertical lining capped coaming
- 2 x Port and starboard sheet cleats
- Teak grating in well sole
- Engine morse control and panel within after hatch
- Cockpit throttle
- Shore power socket
- Deck prisms in deck over chart table
- Steering compass in bridge deck step
- VHF handset

RAISED PILOT CUTTER STYLE COMPANIONWAY HOUSE

TRUNK CABIN

- Varnished companionway hatch
- Varnished iroko butterfly skylight over galley and saloon
- 2 x Dorade boxes and vent cowls

MAST POSITION

- At deck just fwd of trunk cabin
- Gas locker box

FOREDECK

- Offset to port varnished iroko forehatch; bronze portlight
- Deck prisms port and starboard
- Bronze mushroom vent to starboard
- Bowsprit bits
- Bow roller to port of stem
- Bronze Panama fairleads port and starboard

GROUND TACKLE

- Bronze 12 V electric anchor windlass
- Chain gipsy and vertical warping drum
- 33 kg Rocna anchor stored in bow roller (2019)
- Secondary 35 kg Delta anchor stowed on port side
- 60 m Anchor chain
- 40 m Warp rode

Specification

ACCOMMODATION AND DOMESTIC EQUIPMENT

GENERAL

- Oiled Oak and brilliant white gloss painted pine finish
- Oiled pine sole
- Designed to comfortably sleep up to 10 persons (Max. 12)
- Entry via aft and mid companionway hatches
- LED lighting (2019)
- Mattresses with wet weather covers

AFT COMPANIONWAY HOUSE

- Down 4 x steps to
- PILOT CABIN AFT
- Starboard Double Berth
- Port Single Berth
- Oak banquette seating to port
- Access to lazarette (Port and Starboard)
- Navigation area over engine box aft
- Ship's electrical panel (2019)
- Beta engine panel
- Rathmarine VHF Radio with additional handset at hatch
- Rathmarine E80 GPS chart plotter
- Icom 13/C162 hand held VHF
- Raymarine 218E VHF
- EPIRB
- Barometer
- Chart reading light (2019)
- Isotherm 50~L Fridge top loader
- Large hanging locker to port
- 2 x Deck prisms
- 1 x Deckhead lamp
- 2 x Bulkhead lamps

FORWARD TO PORT TO AFT WC/ SHOWER COMPARTMENT

- Also through passage to main saloon

- Seawater wash/ rinse tap
- Athwartships work surface; lifting lids, storage cupboards
- Isotherm 50 L Fridge top loader (2019)
- Athwartships 1.5 inset sinks fwd; mixer tap
- Plate racks; cup hooks; food lockers/ shelves
- Pot lockers
- Skylight in deckhead
- Lemon squeezer deckhead prism

MORSØ 'SQUIRREL' STOVE TO PORT (2019)

- Bookcase over outboard

FORWARD TO SALOON

- Settee berth to port; stowage under
- Generous pilot berth outboard; stowage under
- L-settee to starboard; converts to double berth
- Stowage under
- Generous pilot berth outboard; stowage under
- Large double drop leaf saloon table
- Drinks store under
- Bookcase at forward bulkhead
- Butterfly skylight in deckhead
- Reading lights throughout
- Over head lights throughout
- Oil lamp
- $4 \times Bulkhead lamps$
- 4 x Deckhead lamps
- 4 x Deckhead prisms

MAST POSITION

- Passage forward to port

FORWARD CABIN

- Jabsco Manual Toilet (2019) - Double berth to starboard - Shower (2019) - Single berth with pipe cot over to port - Teak grating sole - Stowage shelves above - Stainless steel basin - Water tanks port and starboard - Mixer tap - Raised forehatch in deckhead - 2 x Lockers - Door to forepeak and forward head - Medical Kit - 2 x Deck prisms - 2 x Bulkhead lamps

- Deck prism in deckhead - 2 x Deckhead lamps

FORWARD TO GALLEY, SALOON & FORWARD ACCOMMODATION

- Jabsco Manual Toilet (2019)

- Shelving

FO'C'SLE

GALLEY TO STARBOARD - Sail and rope stowage - 3 x Burner Force 10 gas hob; grill and oven - Bosun's Locker - 1.5 Inset stainless steel basins - 2 x Deck prisms - Mixer tap - 1 x Bulkhead lamp

Specification

RIG, SAILS AND CANVASWORK

- Gaff Cutter rigged

RIG

- Galvanised mast and spar fittings

- Laminated Longleat Estate Douglas fir mast

- Stepped topmast; single spreader set - Longleat Estate Douglas fir solid boom

- Laminated Douglas fir bowsprit; jib tack traveller

- Chain and tackle bobstay

- Bowsprit shrouds let to tackles port and starboard

- Laminated Douglas fir gaff

- All galvanised 7 x 7 rigging renewed by Dennis Platten (2019)

- All new running rigging by Dennis Platten (2019)

- All blocks checked and re-varnished by Dennis Platten (2019)

SAILS

- Gaff vertical-cut mainsail

- Topsail - Staysail - No. 1 Jib - No. 2 Jib - No. 3 Jib (2019)

CANVASWORK

- Full boat cover over boom to gunwales -

- gooseneck to end of boom & fwd of mast to forestay (2016)

- Sun cover under boom

- Spare water-resistant cushion covers for off shore

Specification

MECHANICAL, ELECTRICAL AND TANKAGE

- Beta Marine BV3300 75 hp diesel

- Aqua Drive and stainless steel propeller shaft (2019)

- Max Prop Three bladed folding bronze propeller (2019)

ELECTRICAL

MECHANICAL

- 12 V Charging system - 4 x House batteries

- 1 x Start batteries

- Electrical panel and fuse board (2019)

- 240 V Shore power (2019)

TANKAGE

- Stainless steel diesel tank; 360 L

- 2 x Stainless steel water tanks; 600 L total

- 12 V Water pressure pump

- Hot water tank aft of engine; c 30 L calorifier/ electric immersion

- Black water holding tank in aft heads; plastic; $50~\mathrm{L}$

Specification

NAVIGATION AND COMMUNICATIONS

NAVIGATION

- Plastimo steering compass

- Raymarine E80 chart plotter

- Raymarine Tridata deck repeater

COMMUNICATIONS

- Raymarine 218E VHF (with deck extension)

- Icom 13/C162 hand held VHF

- 12-Person canister liferaft stowed by mast
- Jon-Buoy (2019)
- Flare pack (2019)
- EPIRB
- 2 x Life rings
- Whale auto bilge pump
- Manual bilge pump at port Pilot berth
- Manual bilge pump in forward cabin

- Engine fire extinguisher (2019)
- Fire extinguishers at all exits and galley
- Fire blanket
- Navigation lights: port, stbd, stern and tri-colour (2019)

Disclaimer

These particulars have been prepared from information provided by the vendors and are intended as a general guide. The purchaser should confirm details of concern to them by survey or engineers inspection. The purchaser should also ensure that the purchase contract properly reflects their concerns and specifies details on which they wish to rely.



ED BURNETT 45 FT GAFF RIGGED PILOT CUTTER 2008/2025

Specification GALLERY















































































































































